

Date: Friday, 13/06/2008 1:48:06 PM
User: Julie Lecocq

ASAP 633-0811 W

Dart Aerospace Ltd.

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: STEP WELDMENT
Job Number	: 39867		
Estimate Number	: 10176		
P.O. Number	:	Part Number	: D2563
This Issue	: 13/06/2008 S.O. No. :	Drawing Number	: D2563 REV C
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: / / Type : LARGE FAB ASSY	Drawing Revision	: C
Previous Run	: 37917A	Material	:
Written By	:	Due Date	: 30/06/2008 Qty: 4 Um: Each
Checked & Approved By	: <u>JUD 08.06.13</u>		
Comment	: Est Rev:G 02.07.31 Re-format Location RF		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D2244116	Step Extrusion
-----	----------	----------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 4.0000 Each(s)

Pick:

1 D2244 Step Extrusion

Batch: 38023

SAD 08/07/24

2.0	D267334	End Plate
-----	---------	-----------



Comment: Qty.: 2.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick:

Qty	Part No.	Description
2	D2673-34	End Cap

Batch

B35887 ✓

SP 08.09.05



3.0	D2561	Lug
-----	-------	-----



Comment: Qty.: 2.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick:

Qty	Part No.	Description
2	D2561	Lug Plate

Batch

B37153 ✓

SP 08.09.05



4.0	D2564	Mounting Angle
-----	-------	----------------



Comment: Qty.: 2.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick:

Qty	Part No.	Description
2	D2564	Mounting Angle

Batch

B38026 ✓

SP 08.09.05



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Friday, 13/06/2008 1:48:06 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP WELDMENT

Job Number: 39867

Part Number: D2563

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

-1-Cut D2244 to 89.70" at 34 deg as per dwg D2563

2-Deburr ends

SAD 08/07/29 (4)

3-Weld (1 END CAP, LUG PLATES & MOUNTING ANGLE) as per dwg D2563 using DT 8343

A/R AL ROD Batch: M108350

M108037

4- Grind

SAD 08/09/08 (4)

SP 08.09. (4K)

6.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

D 08.09.09 (4)

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

S 08/09/09 (4)

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

SAD 08/09/09 (4)

9.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

1/2 08.09.09 4

10.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Inspect for foreign object per QSI 024

2-Weld Remainig End as per Dwg D2563 using DT 8343

A/R AL ROD Batch: M108037

3-Grind SP 08.09.09 (4)

SP 08.09.09 (4K)

SAD 08/09/10 (4)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Friday, 13/06/2008 1:48:07 PM
User: Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP WELDMENT

Job Number: 39867

Part Number: D2563

Job Number:



Seq. #:

Machine Or Operation:

Description :

11.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

PD 08-09-10 (4)

12.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

S 08/09/10 (x4)

13.0

POWDER COATING

POWDER COATING



+pressure wash M 08-09-10
M 108523



Comment: POWDER COATING

Touch up Alodine then

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

START TIME:

8:30AM

OVEN TEMPERATURE:

320°F

FINISH TIME:

9:00AM

→ FL 08/09/10 (4)

M 08-09-10 (x4)

14.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



M 108492



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D2563 and QSI 005 4.4

FL 08/09/10 (4)

15.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



8/9/10 su



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

(4x)

16.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/09/10

Job Completion



PP 40083

8/9/10 su

(4x)

08/09/10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



RELEASED
05.11.28


DESIGN	DRAWN BY	DART AEROSPACE LTD	REV. C
BW	44	HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED	DRAWING NO.	SHEET 1 OF 1
44	44	D2563	SCALE
DATE	TITLE	STEP WELDMENT ASSEMBLY	1:15
05.11.14			
A	96.04.26	NEW ISSUE	
B	97.05.14	END CAPS CHANGED (WAS D2248)	
C	05.11.14	UPDATE NOTES	



D2563 STEP WELDMENT ASSEMBLY PARTS LIST

Part No.	Description	QTY
D2563	STEP WELDMENT ASSEMBLY	X
D2244-89.7	EXTRUSION*	1
D2561	LUG PLATE	2
D2564	MOUNTING ANGLE	2

*cut per drawing



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 998001

D2563 STEP WELDMENT ASSEMBLY NOTES

- 1) MAKE FROM EXTRUSION D2244
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
MASK OFF 0.50 ON EACH SIDE OF D2561 LUGS BEFORE
APPLYING BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED